## EHS Audit - Site Visit Report

Company		MRPLLP Audited by		B Lokesh Kumar		
Site		GMR	Sign	B Lokel		
Project manager name		Srinivas.N/Ahmed	Date	06-09-2024	06-09-2024	
Sign			Previous site visit	date 04-09-2024		
AGH may	by Lokesh atleast once	ATR to be sent to MD (Ashaiya) a week and this report to be sent. nth/quarter. 6. Rating should be g his report.	4. All other sites may be visited	once in two weeks. 5. Sites	like Serene and	
Sl. No.	Description/con	Rating				
1.	Labour complia	Avg				
2.	Tying of safety	Avg				
3.	Material stored	Good				
4.	Engineers awar	Avg				
5.	Maintenance of	Good				
6.	Electrical powe	Avg				
7.	Working of gua	Good				
8.	Working of can	Avg				
9.	Maintenance of	Good				
10.	Safety procedur	Good				
S No.	Suggested recti	ATR required				
1.	Safety nets need					
2.	Cleaning requir					
3.	Electrical wires					
Sl. No.	Suggested impr					
1.						
2.						
3.						
Sl. No.	Suggested improduced Admin/Construction					
1.						
2.						



3.

## EHS Audit - Site Visit Report

Company		Innopolis		Audited by	B Lokech Ku	B Lokesh Kumar				
Site		GVRC		Sign	Blowl	mai				
Project manager name		T Madhu		Date	13-09-2024					
Sign		palle	1	Previous site visit date	04-09-2024					
Note: 1. Original copy of report + ATR to be sent to MD (Ashaiya). 2. This report to be sent on site viber group on same day. 3. All major sites to be visited by Lokesh atleast once a week and this report to be sent. 4. All other sites may be visited once in two weeks. 5. Sites like Serene and AGH may be visited once in a month/quarter. 6. Rating should be good, avg., poor. 7. In ATR required fill Yes/No. 8. Project manager/Engineer must send ATR within 3 days of this report.										
Sl. No.	Description/comp	Rating								
1.	Labour complian	Avg								
2.	Tying of safety n	Avg								
3.	Material stored sa	Good								
4.	Engineers awarer	Avg								
5.	Maintenance of l	Good								
6.	Electrical power	Avg								
7.	Working of guar	Good								
8.	Working of came	Avg								
9.	Maintenance of	Good								
10.	Safety procedure	Good								
S No.	Suggested rectifi	ATR required								
1.	Safety nets need to maintain properly, barricaution required at atrium									
2.	Cleaning required in multiple areas									
3.	Electrical wires joints is there in multiple areas									
Sl. No.	Suggested improvements in SOP (that can be easily taken up)									
1.										
2.										
3.	Cuanatedia	over onto in COI	D (to be im-	plemented after discussion	n with MD/					
Sl. No.	Admin/Construction									
1.	1 Admin Constitute									
2.										
3.										