


List of Pumps at GMR site							
Company:		Modi Reality Mallapur LLP		Approved By :		MD.Ahemedulla khan	
Project :		GMR		Date :		08.10.24	
Prepared By :		SK.Goushee					
Sl No	Details	Item Description	Make	Capacity	Location	Status	Remarks
1	Pump	Openwell submersible pump	Kirloskar	7.5HP	C Block sump Manjeera	Working	
2	Pump	Openwell submersible pump	Kirloskar	10HP	C Block sump Manjeera	Working	
3	Pump	Openwell submersible pump	Kirloskar	3HP	C Block sump Manjeera	Working	
4	Pump	Openwell submersible pump	Kirloskar	7.5HP	C Block sump Bore	Working	
5	Pump	Openwell submersible pump	Kirloskar	10HP	C Block sump Bore	Working	
6	Pump	Openwell submersible pump	Kirloskar	7.5HP	C Block sump Flushing	Working	
7	Pump	Openwell submersible pump	Kirloskar	10HP	C Block sump Flushing	Working	
8	Pump	Openwell submersible pump	KSB	3HP	C Block sump Rainwater	Working	
9	Pump	Openwell submersible pump	KOS	5HP	C Block sump Rainwater	Working	
10	Bore	Submersible pump	KSB	6.5HP	Amphitheatre	Working	
11	Bore	Submersible pump	KSB	6HP	C Block southside	Working	
12	Bore	Submersible pump	-	-	Tranformer Yard	Not Working	
13	Bore	Compressor Pump	Suguna	2HP	Club house southside	Working	
14	Bore	Submersible pump	-	-	G Block northside	Not Working	
15	Pump	Mono block pump	KSB	3HP	Club house stores	Working	
16	pump	Submersible pump	KSB	5HP	E Block lift pit1	Working	
17	pump	Submersible pump	KSB	5HP	E Block lift pit2	Working	
18	pump	Openwell submersible pump	Kirloskar	3HP	E Block Labour quarter Temporary septic tank	Working	
19	pump	Cutter pump	ksb	1.75HP	E Block Labour quarter Temporary septic tank	Working	
20	pump	Cutter pump	KSB	1.75HP	C Block Septick tank	Working	
21	pump	Submersible pump	KSB	7.5HP	Stores	Working	
22	pump	Openwell submersible pump	KSB	5HP	Stores	Working	
23	pump	Dewatering pump	Kirloskar	3HP	E block southside	Working	
25	pump	Dewatering pump	Kirloskar	3HP	E block southside	Working	

Certified By

 Asst. Eng / Admin
 MODI REALTYMALLAPUR LLP

APPROVED BY

 PROJECT MANAGER