EHS Audit - Site Visit Report

Comp	pany	MRPLLP							
Site		GMR	Audited by	B Lokesh Kuma					
Projec	et manager name	Srinivas.N/Ahmed	Sign	To I Kum	N .				
Sign		orativasav Annied	Date	07-10-2024	7				
Note: 1 Original		ATP to be	Previous site visit date	20.09 2024					
be visite	ed by Lokesh atleast once	week and this report to be sent	his paraget to L	group on same day 3	X IX				
must ser	nd ATR within 3 days of the	oth/quarter. 6. Rating should be go	2. This report to be sent on site viber at All other sites may be visited once in ood, avg., poor. 7. In ATR required fill	two weeks, 5. Sites I	ike Serene and				
SI. No	do y Lokesh atleast once a week and this report to be sent. 4. All other sites may be visited once in a month/quarter. 6. Rating should be good, avg., poor. 7. In ATR required fill Yes/No. 8. Project manager/Engineer Description/compliance with safety procedures								
1.	Labour complia	Rating							
2.	Tying of safety	Avg							
3.	Material stored	Avg							
4.	Engineers aware	Good							
5.	Engineers aware	Avg							
6.		Good							
7.	Electrical power Working of guar	Avg							
8.	The Sum	Good							
9.	Working of cam	Avg							
	Maintenance of	Good							
10.	Safety procedure	Good							
S No.	Suggested rectiff	ATR required							
1.	Safety nets need	Arkiequieu							
2.	Cleaning require								
3.	Electrical wires j								
No.	Suggested improvements in SOP (that can be easily taken up)								
1.		Hall Drawnie Livery		7.576					
2.									
3.	370 1 1 1 1 1 1 1 1								
No.	Suggested improvements in SOP (to be implemented after discussion with MD/								
100000000000000000000000000000000000000		Admin/Construction Team/Etc.)							
1.									
2.									
3.									

Almad.

EHS Audit - Site Visit Report

Company		GVRC Audited by B Lokesh ki		B Lokesh kum	ar		
Site		INNOPOLIS	Sign	10-10-2024			
Project manager name		T Madhu	Date	Shopy	4		
Sign		Mallu	Previous site visit date				
be visited AGH may	by Lokesh atleast once	a week and this report to be sent. onth/quarter. 6. Rating should be a	 2. This report to be sent on site viber § All other sites may be visited once in good, avg., poor. 7. In ATR required fill 	two weeks. 5. Sites	like Serene and		
SI. No.	Description/compliance with safety procedures			Rating			
1.	Labour compliance with PPE				Avg		
2.	Tying of safety nets wherever required.				Good		
3.	Material stored	Good					
4.	Engineers awar	Good					
5.	Maintenance of	Good					
6.	Electrical power	Avg					
7.	Working of gua	Good					
8.	Working of car	Avg					
9.	Maintenance of	Good					
10.	Safety procedur	Good					
S No.	Suggested recti	ATR required					
1.	DP boxes are no						
2.	3600 block safe						
3.	3600 block stair						
Sl. No.	Suggested improvements in SOP (that can be easily taken up)						
1.					A CANADA		
2.							
3.							
Sl. No.	Suggested impre Admin/Construc						
1.							
2.		FRESH AND THE RES					
3.							