

ACCEPTANCE FORM

Customer Copy

LR ORDER COMPLETION



JOHNSON LIFTS PRIVATE LIMITED

PLOT NO.B-31 (PART) TIE, BALANAGAR, HYDERABAD

Phone : 040-23078881, 23078882, 230788

QR.No For Lift :SERV/08/QR/04

Customer : GREENWOOD WELFARE ASSOCIATIONS.
GREENWOOD HEIGHTS
SURVEY NO.196, KOWKUR ,
HYDERABAD 500010

Quotation No. QTN20240900873

Date. 19-OCT-2024

Job No. L-Q2727

SM No. SMI2579

Service Type. PSM

LR No. LR_L-Q2727_273382

Mechanic Deputed S
TARRA ESWARA RAO

We have completed the work on the elevator / escalator as per our quotation No. QTN20240900873

The work is completed in a satisfactory manner and we hereby request to accept the same.

Remarks if any:

Customer Name :

Signature :

Contact No :

Date : 19/10/2024

Johnson Representative : J. Eswara Rao

Signature : *[Signature]*

Time Reported

4:00


Time Left

5:30

CAUTION : IF DOOR OPEN KEY IS USED ENSURE THAT DOOR IS FULLY CLOSED.

Regd. Office : No.1 East Main Road, Anna Nagar Western Extension, Chennai - 600 101. Grams : LIFTS Fax : 91-44-26151614

Website : www.johnsonliftsltd.com Ph: 26152003, 26152004, 26152005, 26152006



Scanned with OKEN Scanner

Johnson Lifts Private Limited

SERV/07/QR/02

BREAK DOWN REPORT

Location / Address

B/D Report No. 28527

Lift No.

Greenwood Wellbore
LQ 2727

Date :

19/10/2024

TYPE OF B/D

REMARKS / DETAILS

- Q1 ☒ Lift not working
- Q2 ☐ Lift working with problems
- Q3 ☐ Repeated Break down

AREA OF B/D

- 01 Doors / Locks
- 02 M/C Room equipment
- 03 Controller : Relays wiring
- 04 Controller : PCB's
- 05 Trailing Cable / Shaft wiring
- 06 OSG / Safety Gear / Safety CKT's
- 07 Incoming power supply

Dear Sir,
Please note that we have
Replaced. New door motor
for the lift working good
condition and also stating
to you. This is for
Low voltage / One phase failure
Unbalance voltage / Phase link/
Phase Reverse

Substitution.

- 08 Others
- 09 Incoming Main Switch / Overload trip
- 10 User Attention

RECTIFICATION

Parts replaced :

- 01 ☒ Rectified - working
- 02 ☐ Shut down for want of material
- 03 ☐ OK on call
- 04 ☐ Attention needed during servicing

Door motor.

Customer Reported on (Date & Time)

Team arrival time at site

Lift put back in operation at

Technician / Engineer

Signature

Customer Signature

WARD	
16568	22/10/24
No:	Dr:
Bishnu Msh	
19/10/2024	

