EHS Audit - Site Visit Report

Comp	pany	MRPLLP	Audited by	B Lokesh Kuma	ar
Site		GMR	Sign	P. Ward	
Projec	et manager name	Srinivas N/Ahmed	Date	04-12-2024	
Sign		Alumed:	Previous site visit date	26-11-2024	
AGH m	ay be visited once in a mont and ATR within 3 days of this	week and this report to be sent. 4	2. This report to be sent on site viber All other sites may be visited once in d, avg., poor. 7. In ATR required fill	two weeks 5 Sites I	ka Sarana and
Sl. No		liance with safety procedures		Rating	
1.	Labour compliance with PPE		·		Avg
2.	Tying of safety nets wherever required.			Avg	
3.		Material stored safely and properly.			
4.		Engineers awareness and compliance with safety procedures including their PPE.			
5.	Maintenance of labour quarters, cleanliness, provision of toilets & water supply.				Good
6.	Electrical power supply for construction activity, pumps, temporary lighting.				Avg
7.	Working of guard siren.				Good
8.	Working of camer	Avg			
9.	Maintenance of cr	Avg			
10.	Safety procedures	Good			
S No.	Suggested rectification	ATR required			
1.	Safety nets need to maintain properly,				
2.	Cleaning required in multiple areas				
3.					
Sl. No.	Suggested improvements in SOP (that can be easily taken up)				
1.					
2.	-				
3.					
Sl. No.	Suggested improve Admin/Construction				
1.					
2.					
3.					

June.

EHS Audit - Site Visit Report

Compa	ny	Innopolis Audited by B L		B Lokesh kum	Lokesh kumar		
Site		GVRC	Sign	R. both			
Project manager name		T Madhu	Date	04-12-2024			
Sign		Jaelle	Previous site visit date				
AGH may	be visited once in a mon ATR within 3 days of the	on the control of the sent. And this report to be sent. Another the sent of th	o. 2. This report to be sent on site viber 4. All other sites may be visited once is lood, avg., poor. 7. In ATR required fil	n true mealer 5 Citan	Lilea Canama and		
SI. No.	Description/compliance with safety procedures				Rating		
1.	Labour compliance with PPE				Avg		
2.	Tying of safety	Avg					
3.	Material stored	Good					
4.	Engineers award	Good					
5.	Maintenance of	Good					
6.	Electrical power	Avg					
7.	Working of gua	Good					
8.	Working of cam	Avg					
9.	Maintenance of	Good					
10.	Safety procedur	Avg					
S No.	Suggested rectif	ATR required					
1.	Safety nets need						
2.	Barriacaution re	BASSAN S					
3.	Safety materal of						
Sl. No.	Suggested improvements in SOP (that can be easily taken up)						
1.							
2.							
3.				And the second			
Sl. No.	Suggested impro Admin/Construction						
1.					N CONTRACTOR		
2.							
3.							