EHS Audit - Site Visit Report

Company		Innopolis	Audited by	BARRANAED BY		
Site		GVRC	Sign	100 JAN 2027		
Project manager name		T Madhu	Date	08-01-2025	WOU'L DER	
Sion		- ver	✓ Previous site visit date	02-01-2024	CT MANCES	
be visited AGH may	Land and and an area	a week and this report to be sent. 4 nth/quarter. 6. Rating should be go	2. This report to be sent on site viber. All other sites may be visited once in lood, avg., poor. 7. In ATR required fill	CWU WOLLS. J. DRES	nanager/Engineer	
Sl. No.					Rating	
1.	Labour compliance with PPE				Good	
2.	Tying of safety	Avg				
3.	Material stored	Good				
4.	Engineers' awa	Good				
5.	Maintenance of	Good				
6.	Electrical power	Good				
7.	Working of gua	Avg				
8.	Working of can	Avg				
9,	Maintenance of	Good				
10.	Safety procedur	Avg				
S No.	Suggested recti	ATR required				
1.	3600 block duc					
2.	Barri-cation required at cable vault					
3.						
Sl. No.	Suggested impr					
1.						
2.						
3.			1 1 2 1	id May		
Sl. No.	Suggested impro Admin/Construction					
1.						
4.	Late of the same of the same of					

EHS Audit – Site Visit Report

Company		Gmr	Audited by	B Lokesh kum	ar					
Site		Gmr	Sign	Lokest	Cokest					
Project manager name		Amhed/srinivas\	Date	08-01-2025						
Sign		Almed	Previous site visit date	02-01-2024						
Note: 1. Original copy of report + ATR to be sent to MD (Ashaiya). 2. This report to be sent on site viber group on same day. 3. All major sites to be visited by Lokesh atleast once a week and this report to be sent. 4. All other sites may be visited once in two weeks. 5. Sites like Serene and AGH may be visited once in a month/quarter. 6. Rating should be good, avg., poor. 7. In ATR required fill Yes/No. 8. Project manager/Engineer must send ATR within 3 days of this report.										
Sl. No.	Description/com	Rating								
1.	Labour complian	Good								
2.	Tying of safety i	Avg								
3.	Material stored s	Good								
4.	Engineers' awar	Good								
5.	Maintenance of	Good								
6.	Electrical power	Good								
7.	Working of guar	Avg								
8.	Working of cam	Avg								
9.	Maintenance of	Good								
10.	Safety procedure	Avg								
S No.	Suggested rectif	ATR required								
1.	Labour quarters									
2.	H block Safety nets need to tie properly									
3.										
Sl. No.	Suggested improvements in SOP (that can be easily taken up)									
2.										
3.										
Sl. No.	Suggested impr Admin/Construc									
1.		,								
2.										
3.										