





EHS Audit – Site Visit Report

Company	MRPLLP	Audited by	B LOKESH
Site	GMR	Sign	
Project manager name	AHMED	Date	03-04-2025
Sign		Previous site visit date	07-03-2025

Note: 1. Original copy of report + ATR to be sent to MD (Ashaiya). 2. This report to be sent on site vibser group on same day. 3. All major sites to be visited by Lokesh atleast once a week and this report to be sent. 4. All other sites may be visited once in two weeks. 5. Sites like Serene and AGH may be visited once in a month/quarter. 6. Rating should be good, avg., poor. 7. In ATR required fill Yes/No. 8. Project manager/Engineer must send ATR within 3 days of this report.

Sl. No.	Description/compliance with safety procedures	Rating
1.	Labour compliance with PPE	Avg
2.	Tying of safety nets wherever required.	Good
3.	Material stored safely and properly.	Good
4.	Engineers awareness and compliance with safety procedures including their PPE.	Good
5.	Maintenance of labour quarters, cleanliness, provision of toilets & water supply.	Good
6.	Electrical power supply for construction activity, pumps, temporary lighting.	Good
7.	Working of guard siren.	Good
8.	Working of cameras + power supply to cameras.	Good
9.	Maintenance of creche, creche teacher, mid-day meals.	Good
10.	Safety procedures for earth work including earth storage, barricading, shoring.	Good
S No.	Suggested rectifications/corrections	ATR required
1.	Labour quarters cleaning required	
2.	Finishing stage PPE labour need to maintain compulsory	
3.		
Sl. No.	Suggested improvements in SOP (that can be easily taken up)	
1.		
2.		
3.		
Sl. No.	Suggested improvements in SOP (to be implemented after discussion with MD/ Admin/Construction Team/Etc.)	
1.		
2.		
3.		

EHS Audit – Site Visit Report

Company	GVRC	Audited by	B LOKESH
Site	Innopolis	Sign	
Project manager name	T Madhu	Date	04-04-2025
Sign		Previous site visit date	025-03-2025

Note: 1. Original copy of report + ATR to be sent to MD (Ashaiya). 2. This report to be sent on site viber group on same day. 3. All major sites to be visited by Lokesh atleast once a week and this report to be sent. 4. All other sites may be visited once in two weeks. 5. Sites like Serene and AGH may be visited once in a month/quarter. 6. Rating should be good, avg., poor. 7. In ATR required fill Yes/No. 8. Project manager/Engineer must send ATR within 3 days of this report.

Sl. No.	Description/compliance with safety procedures	Rating
1.	Labour compliance with PPE	Avg
2.	Tying of safety nets wherever required.	Good
3.	Material stored safely and properly.	Good
4.	Engineers awareness and compliance with safety procedures including their PPE.	Good
5.	Maintenance of labour quarters, cleanliness, provision of toilets & water supply.	Good
6.	Electrical power supply for construction activity, pumps, temporary lighting.	Good
7.	Working of guard siren.	Avg
8.	Working of cameras + power supply to cameras.	Good
9.	Maintenance of creche, creche teacher, mid-day meals.	Good
10.	Safety procedures for earth work including earth storage, barricading, shoring.	Good
S No.	Suggested rectifications/corrections	ATR required
1.	PPE Need to follow compulsory	
2.	Safety nets need tie properly at 3600 block	
3.		
Sl. No.	Suggested improvements in SOP (that can be easily taken up)	
1.		
2.		
3.		
Sl. No.	Suggested improvements in SOP (to be implemented after discussion with MD/ Admin/Construction Team/Etc.)	
1.		
2.		
3.		