EHS Audit - Site Visit Report

Company		GVRC Audited by		B LOKESH			
Site		Innopolis	Sign	Viba			
Project manager name		T Madhu	Date	14-04-2025			
Sign		Jan. New	Previous site visit date	04-04-2025			
AGH may must send	be visited once in a mo ATR within 3 days of the	nth/quarter. 6. Rating should I his report.	niya). 2. This report to be sent on site viber mt. 4. All other sites may be visited once in be good, avg., poor. 7. In ATR required fill	group on same day, two weeks, 5. Sites Yes/No. 8. Project of	3. All major sites to like Serene and manager/Engineer		
Sl. No.	Description/cor	Rating					
1.	Labour complia	Avg					
2.	Tying of safety	Good					
3.	Material stored	Good					
4.	Engineers awar	Good					
5,	Maintenance of	Good					
6.	Electrical powe	Good					
7.	Working of gua	Avg					
8.	Working of can	Good					
9.	Maintenance of	Good					
10.	Safety procedur	Good					
S No.	Suggested rectif	ATR required					
1.	PPE Need to foll						
2.	Safety nets need tie properly at 3600 block						
3.							
sl. No.	Suggested impre						
1.							
2.							
3.							
Sl. No.	Suggested impro						
1.							
2.							
3.							

EHS Audit - Site Visit Report

And the second second second	MATERIAL SERVICE SERVI					
Company		NGH	Audited by	B LOKESH		
Site		NGH	Sign	MZI L		
Project manager name		Vijay raj	Date	15-04-2025		
Sign		7	Previous site visit date	04.02.2024		
AGH may must send	be visited once in a mor ATR within 3 days of the	oth/quarter, 6. Rating shoul its report.	shaiya). 2. This report to be sent on site viber sent. 4. All other sites may be visited once in ld be good, avg., poor. 7. In ATR required fill	group on same day. I two weeks. 5. Sites Yes/No. 8. Project	All major sites to like Serone and manager Engineer	
Sl. No.	Description/con	Rating				
1.	Labour complia	Avg				
2.	Tying of safety	Good				
3.	Material stored safely and properly.					
4.	Engineers award	Good				
5.	Maintenance of	Good				
6.	Electrical power	Good				
7.	Working of guar	Avg				
8.	Working of cameras + power supply to cameras.					
9.	Maintenance of creche, creche teacher, mid-day meals.					
10.		Good				
S No.	Safety procedures for earth work including earth storage, barricading, shoring. Suggested rectifications/corrections					
1.	PPE Need to follo	ATR require				
	Labour quarters c					
3.					E Back to China	
l. No.	Suggested impro	100000000000000000000000000000000000000				
1.						
2.						
3.						
Il. No.	Suggested impro Admin/Construct					
1.						
2.					7.78	
3.					SECTION AND	