EHS Audit - Site Visit Report

Compa	ny	SOV3	Audited by	B Lokesh Kur	nar
Site		SOV	Sign	RLA	L
Project manager name		Purushotham	Date	03-05-2025	1
Sign		D.J.	Previous site visit	date 17-04-2025	
AGH may	and many on town chief &	Charter 6 Pating should be	ya). 2. This report to be sent on site nt. 4. All other sites may be visited e good, avg., poor. 7. In ATR requi	viber group on same day.	HKE SELCTIO
Sl. No.	Description/comp	Rating			
1.	Labour complian	Avg			
2.	Tying of safety n	Avg			
3.	Material stored sa	Good			
4.	Engineers awarer	Avg			
5.	Maintenance of la	Good			
6.	Electrical power	Avg			
7.	Working of guard	Good			
8.	Working of came	Avg			
9.	Maintenance of c	Good			
10.	Safety procedure	Good			
S No.	Suggested rectific	ATR required			
1.		d in multiple areas			
2.	Labour quarters s				
3.	Eurour quarters s	arrounding cleaning	required		
SI. No.	Suggested improv	vements in SOP (that	can be easily taken up)		
1.					
2.					
3.					
SI. No.	Suggested improve Admin/Construction				
1.					
2.					
3.					

EHS Audit – Site Visit Report

Compa	ny	CVIDG					
Site		GVRC	Audited by	Audited by		nar	
Project manager name		Innopolis	Sign		Claus		
Sign		T Madhu	Date		03-05-2025		
Note: 1. Original compact		Mary		HONE MINES	12-04-2025		
AGH ma	v be visited once in a month	to and and report t	(Ashaiya). 2. This report to be so be sent. 4. All other sites may lould be good, avg., poor. 7. In A	ent on site viber g be visited once in	roup on same day two weeks. 5. Sites	like Serene and	
must sen	d ATR within 3 days of this	report.	round be good, avg., poor. 7. In A	TR required fill	res/No. 8. Project r	nanager/Englice:	
Sl. No.	- compared comp	Rating					
1.	Labour compliance	Avg					
2.	Tying of safety ne	Avg					
3.		Material stored safely and properly.					
4.	Engineers awarene	Engineers awareness and compliance with safety procedures including their PPE.					
5.	Maintenance of la	Good					
6.	Electrical power s	Avg					
7.	Working of guard	Good					
8.	Working of camer	Avg					
9.	Maintenance of cr	Good					
10.	Safety procedures	Good					
S No.	Suggested rectification	ATR required					
1.	Cleaning required						
2.	Electrical wires jo properly						
3.	3600 block safety						
il. No.	Suggested improve						
1.							
2.							
3.					'al MD/		
SI. No.	Suggested improvements in SOP (to be implemented after discussion with MD/ Admin/Construction Team/Etc.)						
1.							
1. 2.							