

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1005**

Date : 14.09.2019.

Inspection of Footings Block A C1-E1/1-5, Block B
B' - P / 12-19.

- (1) Footing and column reinforcement checked and found correct and as per the structural drawings.
- (2) Complete remaining shuttering removed and then proceed with concrete pouring.

14/9/19

NOTE:- Provide (additional) dowel/anchors for elevated footings. Use nominal steel reinforcement mat of 2% for footings on walls with steep soil slopes.

Engineer Sign.

Consultant Sign.

Mohammed Azheruddin

Date :

Date : 14/09/2019

Zaki & ASSO.