

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No.

1017Date : 05.02.2020

*Inspection of Soil Stabilization in Block 'C'
for foundation.*

- Boulder filling completed, Muram Filling started. One layer of Muram (48") is laid. remaining depth to be filled is 5'0".
- Sand should be filled upto a thickness of 3'0" above Muram level.
- Sand bed should be well compacted
- Follow Stabilization process mentioned in the Soil report.

Engineer Sign.

Date :

[Signature]
05/02/2020

Consultant Sign.

Date :

[Signature]
Mohammed Akbaruddin
Zaki & Associates