

OUTWARD - GATE PASS

No.: 13473

Date :	21/12/19	Time :	10:30
Company :	Silver Oak Villas LLP		
Project/site :	SOV Phase - 12		
Destination :	S. R Engineering		
Outward No. :	Vehicle type	Vehicle No	Owner / Person
10910	TATA AC	TS03UE 7192	Venkatesh
	Material Description	Quantity	Units
1.	M-S Railing 9'8"x1'3"	06	Nos
2.	- do - 10'6"x1'8"	31	"
3.	- do - 12'x1'6"	08	"
4.	- do - 10'x2'6"	04	"
5.			
6.			
7.			
8.			
9.			
10.			
	Total	49	Nos
Purpose	☐ Return to Supplier ☒ Transfer to other site ☐ For repair/service ☐ Transfer for other phase ☐ On loan to be returned ☐ Others :		
Charges :	☐ No Charge ☐ Collect Full Value ☐ Used/Old Material-Collected 60% value ☐ No charge material shall be reimbursed by fresh PO ☐ Other :		
Material type	☐ Used ☒ New ☐ Defective ☐ Other :		
Remarks :	For powder Coated purpose.		
Approved by :	Sr. Engg.	Admin In-charge	Security
Sign.			
Received on	Inward No.	Admin sign:	Security sign.

Note : 1. In case of long list attach a separate signed list 2. Approx rate & amount to be filled by purchase. 3. Original (white copy) to be sent with material to recipient site. Recipient must sign it and send it to the HO 4. Pink copy to be sent to HO-Purchase division. 5. In units enter nos, kgs, sft, rft, etc. 6. Project manager / Sr. Engg and Admin in-charge from the issuing site must sign the gate pass.

OUTWARD - GATE PASS

No.: 13474

Date :	23/12/19	Time :	10:10
Company :	Silver Oak Villas LLP		
Project/site :	Sov phase - 1A		
Destination :	Nilgiri Estates		
Outward No. :	Vehicle type	Vehicle No	Owner / Person
10910	By bike	Active	Sandesh Babu
	Material Description	Quantity	Units
1.	open well pump	01	N/A
2.	(1 HP)		
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
	Total	01	N/A
Purpose	☐ Return to Supplier ☒ Transfer to other site ☐ For repair/service ☐ Transfer for other phase ☐ On loan to be returned ☐ Others :		
Charges :	☐ No Charge ☐ Collect Full Value ☐ Used/Old Material-Collected 60% value ☐ No charge material shall be reimbursed by fresh PO ☐ Other :		
Material type	☒ Used ☐ New ☐ Defective ☐ Other :		
Remarks :	Sending to NI-E Site on loan to be Returned		
Approved by :	Sr. Engg.	Admin In-charge	Security
Sign.			
Received on	Inward No.	Admin sign:	Security sign.

Note : 1. In case of long list attach a separate signed list 2. Approx rate & amount to be filled by purchase. 3. Original (white copy) to be sent with material to recipient site. Recipient must sign it and send it to the HO 4. Pink copy to be sent to HO-Purchase division. 5. In units enter nos, kgs, sft, rft, etc. 6. Project manager / Sr. Engg and Admin in-charge from the issuing site must sign the gate pass.

OUTWARD - GATE PASS

No.: 13475

Date :	23/12/15	Time :	18:00		
Company :	Silver Oak Villas LLC				
Project/site :	Sav Phase - 12				
Destination :	Plot No. 280 Jubhills				
Outward No. :	Vehicle type	Vehicle No	Owner / Person		
10911	By bike	TS 10 CC 152	P. Somach		
	Material Description	Quantity	Units	Approx. rate	Amount
1.	MT Camera kit	02	Nr		
2.					
3.					
4.					
5.					
6.					
7.					
8.					
9.					
10.					
	Total	02	Nr		
Purpose	☐ Return to Supplier ☐ Transfer to other site ☐ For repair/service ☐ Transfer for other phase ☒ On loan to be returned ☐ Others :				
Charges :	☒ No Charge ☐ Collect Full Value ☐ Used/Old Material-Collected 60% value ☐ No charge material shall be reimbursed by fresh PO ☐ Other :				
Material type	☐ Used ☒ New ☐ Defective ☐ Other :				
Remarks :	On loan to be Returned As per system admin advice.				
Approved by :	Sr. Engg.	Admin In-charge	Security		
Sign.					
Received on	Inward No.	Admin sign:	Security sign		

Note : 1. In case of long list attach a separate signed list 2. Approx rate & amount to be filled by purchase. 3. Original (white copy) to be sent with material to recipient site. Recipient must sign it and send it to the HO 4. Pink copy to be sent to HO-Purchase division. 5. In units enter nos, kgs, sft, rft, etc. 6. Project manager / Sr. Engg and Admin in-charge from the issuing site must sign the gate pass.

OUTWARD - GATE PASS

No.: 13476

Date :	28/12/19	Time :	10:45		
Company :	Silver Oaks Villas LLP				
Project/site :	Sov Phase - 1 st				
Destination :	May Flower platinum				
Outward No. :	Vehicle type	Vehicle No	Owner / Person		
10912	Tractor	AP36X 5848	Ramachandran		
	Material Description	Quantity	Units	Approx. rate	Amount
1.	old panel door (24x80)	13	Nos		
2.	- do (32x80)	07	"		
3.	- do (36x80)	02	"		
4.					
5.					
6.					
7.					
8.					
9.					
10.					
	Total	22	Nos		
Purpose	☐ Return to Supplier ☒ Transfer to other site ☐ For repair/service ☐ Transfer for other phase ☐ On loan to be returned ☐ Others :				
Charges :	☒ No Charge ☐ Collect Full Value ☐ Used/Old Material-Collected 60% value ☐ No charge material shall be reimbursed by fresh PO ☐ Other :				
Material type	☒ Used ☐ New ☐ Defective ☐ Other :				
Remarks :	Sending to mpc site				
Approved by :	(Sr. Engg.	Admin In-charge	Security		
Sign.					
Received on	Inward No.	Admin sign:	Security sign.		

Note : 1. In case of long list attach a separate signed list 2. Approx rate & amount to be filled by purchase. 3. Original (white copy) to be sent with material to recipient site. Recipient must sign it and send it to the HO 4. Pink copy to be sent to HO-Purchase division. 5. In units enter nos, kgs, sft, rft, etc. 6. Project manager / Sr. Engg and Admin in-charge from the issuing site must sign the gate pass.