



**Subject** Audit observations of Electric power supply/sub-meters  
**From** padmanabha <padmanabha@modiproperties.com>  
**To:** sohammodi@modiproperties.com <sohammodi@modiproperties.com>  
**Cc:** madhu@modiproperties.com <madhu@modiproperties.com>, balakrishna@modiproperties.com <balakrishna@modiproperties.com>, shirish@modiproperties.com <shirish@modiproperties.com>, andrews@modiproperties.com <andrews@modiproperties.com>

**Date** Wed, Sep 27, 2017 at 2:59 PM

Dear Sir,

The following are the observations of audit.

1) Paramount Avenue: The electrical registers and other parameters have been checked and found satisfactory except two distribution boxes are found in open condition in the cellar area. The closing of doors needs immediate attention.

2) Vista Homes: All the parameters have been found satisfactory.

Regards,

V B Padmanabha Rao

Liaison Manager | +91 73311 20727 | [padmanabha@modiproperties.com](mailto:padmanabha@modiproperties.com)  
Modi Properties Pvt. Ltd. | [www.modiproperties.com](http://www.modiproperties.com)

5-4-187/ 3 & 4, M G Road, Secunderabad -03 | Ph: +91 40 6633 5551

Don't just buy a flat or villa! Buy a great lifestyle!

We build affordable flats & villas in gated communities.

No  
impedance  
in  
the  
way