

Company:	MRM(LLP)
Project & Phase:	AGH
Prepared by:	Sunil
Report Date:	1/6/2020
Sign:	
Check list for QC at each stage.	
Notes:	
1. Report should be send once a quarter on or before 15th of the succeeding month.	
2. Where QC was done write the QC report number if available or mark a 'tick'	
3. Mark 'X' if QC check was missed and can be taken up now. Project Manager to send request immediately.	
4. Mark 'XX' if QC check was missed and cannot be undertaken now.	
5. Mark 'NA' if QC check was not applicable (work done before QC was introduced).	
6. Leave blank if work has not taken up.	
Remarks:	
Villa no= 49,50,51,90,54,55,78,40,41,66,75,77,86,38,39,31,29,65,67,68,33,34,15,26,89,53,44	
85,47,59,83,36,1,18,19,24,25,43,45,46,52.(Footings) QC checkings are not done due to water Stagnated in Pits.	
For above Villas Exemption given by MD sir to cast the Footings with out QC check.	

Certified by

Asst. Project Manager/Engineer,
Modi Realty (Miryalaguda) LLP

Works - Villas														
S No	Block / Villa No	Before footings	Plinth	Col 1	Slab 1	Col 2	Slab 2	Col 3	Slab 3	Col 4	Slab 4	Col 5	Slab 5	Col 6
1	B.No-01		34504	34553	34932	35024								
2	B.No-02	27344	27979	28295	28467	28545	28571	29187	29188					
3	B.No-03	27244	27929	28232	28424	28757	28792							
4	B.No-04	27219	27767	28233	28324	28756	28793							
5	B.No-05	26848	27606	27999	28520	28754	28912							
6	B.No-06	27170	27660	29823	30007	30093	30267	30290	30309					
7	B.No-07	27135	27721	27998/29824	30114	30212	30308	30379	30381					
8	B.No-08													
9	B.No-09	28121	28184	28325	28546	28855	28913							
10	B.No-10	31270	31867	31997	32446	32417	32556							
11	B.No-11	31304	31821	32060	32273	32329	32408							
12	B.No-12	31027	31453	31659	31868	31998	32061							
13	B.No-13	31061	31437	31535	31700	31766	31902							
14	B.No-14	31077	32133	32200	32555	32620	32621							
15	B.No-15		34030	34113	34172	34212	34263	34332	34354					
16	B.No-16	31012	32162	32272	32502	32571	32668	32818	32842					
17	B.No-17	31116	32303	32380	32593	32694	32695							

Certified by

Asst. Project Manager/Engineer
Modi Realty (Mittalaguda) LLP

S No	Block / Villa No	Before footings	Pirinth	Col 1	Slab 1	Col 2	Slab 2	Col 3	Slab 3	Col 4	Slab 4	Col 5	Slab 5	Col 6
18	B.No-18		34758	34900										
19	B.No-19		34783	34861										
20	B.No-20	31337	32575	32619	32780	32820	32868							
21	B.No-21	28124	28185	28326	28648	28856	29158							
22	B.No-22	27726	28047	28468	28791	28986	29159							
23	B.No-23	31152	32841	32913	33348	33567	33772	33824	33864					
24	B.No-24		34805											
25	B.No-25													
26	B.No-26		34907	34954										
27	B.No-27	31321	32169	32301										
28	B.No-28	31250	32211	32302										
29	B.No-29		32804	32861	32978	33012	33064							
30	B.No-30	27691	28425	28497	29556	29695	29747							
31	B.No-31		32819	32885	33073	33139	33177							
32	B.No-32	28015	28649	28747	28835	28985	29157	29261	29448					
33	B.No-33		33789	33866	34043	34114	34140							
34	B.No-34		33780	33823	33908	33949	33999							
35	B.No-35	28055	28153	28297	28748	28914	29259							

Certified by

Aest. Project Manager/Engineer
Modi Realty (Mityalaguda) LLP

S No	Block / Villa No.	Before footings	Plinth	Col 1	Slab 1	Col 2	Slab 2	Col 3	Slab 3	Col 4	Slab 4	Col 5	Slab 5	Col 6
36	B.No-36		34298	34417	34953									
37	B.No-37	28043	28444	28519	28724	28915	29260							
38	B.No-38		33014	33072	33154	33180	33274	33371	33381					
39	B.No-39		33003	33033	33109	33140	33226	33269	33289					
40	B.No-40		30784	30841	32333	32407	32928	32976	33004					
41	B.No-41		30660	30783	31480	31608	31633							
42	B.No-42	31196	34714	34824										
43	B.No-43		34666	34724	34777	34842	34870	34931	34983					
44	B.No-44		34637	34697	35035									
45	B.No-45		34605	34684										
46	B.No-46		34555	34635										
47	B.No-47		34415	34471	34509	34658	34699	34733	34755					
48	B.No-48	28122	28296	28374	28944	29131	29560							
49	B.No-49		34227	34297	34754	34810	34853	34901	34967					
50	B.No-50		34317	34414	34990									
51	B.No-51		34254	34330										
52	B.No-52		34483	34606										
53	B.No-53		34279	34331										

Certified by

 Asst. Project Manager/Engineer
 Modi Realty (Miryalaguda) LLP

Quarterly Report AGH -06-01-20.xls

S No	Block / Villa No	Before footings	Plinth	Col 1	Slab 1	Col 2	Slab 2	Col 3	Slab 3	Col 4	Slab 4	Col 5	Slab 5	Col 6
54	B No-54		34472	34607										
55	B No-55		34213	34255	34407	34444	34560	34657	34688					
56	B No-56	31179	32549	32618	33948	34031	34081							
57	B No-57	28339	28517	28623	29365	29557	29786							
58	B No-58	30965	31206	31303										
59	B No-59		33956	34006	34193	34226	34288	34335	34362					
60	B No-60	30933	31231	31334	33803	33863	33974							
61	B No-61	28077	28215	28327	29875	30058	30094							
62	B No-62	28386	28678	28790	29438	29602	29693							
63	B No-63	28443	28723	28837	29189	29349	29559							
64	B No-64	28078	28216	28362	28910	29130	29439							
65	B No-65		30901	30931	31658	31751	31958	32062	32081					
66	B No-66		30734	30900	31765	31901	32125	32234	32263					
67	B No-67		30932	31011										
68	B No-68		32702	32847	34475	34554	34665	34723	34730					
69	B No-69	30733	30966	31060	33865	33923	33998	34079	34111					
70	B No-70	30760	30982	31117	33825	33893	33973	34044	34112					
71	B No-71	28044	30761	30861	31197	31335	31336							

Certified by

 Asst. Project Manager/Engineer
 Modl Realty (Miryalaguda) LLP

S No	Block / Villa No.	Before footings	Plinth	Col 1	Slab 1	Col 2	Slab 2	Col 3	Slab 3	Col 4	Slab 4	Col 5	Slab 5	Col 6
72	B.No-72	31139	32080	32170										
73	B.No-73	30785	31059	31151	31581	31699	31752							
74	B.No-74	28154	28340	28445	29746	29877	29878							
75	B.No-75		30564	30661	31418	31510	31511							
76	B.No-76	28387	28624	28725	29692	29856	29876							
77	B.No-77		29696	29855	30211	30249	30265							
78	B.No-78		33926	34000	34090	34138	34211							
79	B.No-79	28378	28494	28573	29493	29694	29787							
80	B.No-80	28377	28572	28677	29244	29492	29788							
81	B.No-81	30818	31078	31176	34167	34256	34318	34360	34416					
82	B.No-82	30902	31251	31386	34139	34166	34236	34295	34296					
83	B.No-83		33822	33924	34346	34447	34491							
84	B.No-84	30843	31271	31509	31731	31900	31959							
85	B.No-85		33894	33925	34722	34778	34803	34871	34902					
86	B.No-86		30515	30626	31029	31198	31230							
87	B.No-87	30862	31302	31680	32381	32469	32470							
88	B.No-88	28329	28466	28547	30378	30449	30450							
89	B.No-89		34361	34445	34735	34804	34826	34903	34904					

Certified by




 Asst. Project Manager/Engineer
 Modi Realty (Miryalaguda) LLP

S No	Block / Villa No	Before footings	Plinth	Col 1	Slab 1	Col 2	Slab 2	Col 3	Slab 3	Col 4	Slab 4	Col 5	Slab 5	Col 6
90	B.No-90		34347	34402	34446	34503	34604	34659	34696					
91	B.No-91	28426	29601	30055	30654	30762	30763							
92	B.No-92	30323	30712	30815	32063	32144	32262	32330	32331					
93	Club-house	30565	32347	32942	33682	33779	33941	34080	34180	34303	34482	34636	34712	34756
94	Swimming pool			34973										

Certified by

Asst. Project Manager/Engineer
Modi Realty (Miyalaguda) LLP

Civil Works						
S No.	Block /Flat No	After brick work	After Plastering	Stage I, Plumbing & electrical	Stage II	Stage III
1	B No-01					31420
2	B No-02	29306	30050	30052	31153	31421
3	B No-03	29307	30053	30054	31338	
4	B No-04	29346	30110			
5	B No-05	29366	30213			
6	B No-06	32914	33462			
7	B No-07	33098	33463			
8	B No-08					34032
9	B No-09	29491	30268	31999	33270	
10	B No-10	34144				
11	B No-11	33771	34042			
12	B No-12					
13	B No-13					
14	B No-14					
15	B No-15					
16	B No-16					
17	B No-17	34966				
18	B No-18					
19	B No-19					
20	B No-20					34049
21	B No-21	29630	30291	32289	33290	34192
22	B No-22	29631	30352	31209	33110	
23	B No-23					
24	B No-24					
25	B No-25					
26	B No-26					
27	B No-27					
28	B No-28					
29	B No-29	34091	34319			
30	B No-30	31634	32232	32774	33464	34195
31	B No-31	34253	34974			
32	B No-32	30269	30516	32000	33828	34215
33	B No-33	34713	34930			
34	B No-34	34533	34734			
35	B No-35	30964	31582	32057	34561	34952
36	B No-36					
37	B No-37	31698	32338	33827	34639	34975
38	B No-38	34776				
39	B No-39	34683				
40	B No-40					
41	B No-41	32994	33826			
42	B No-42					
43	B No-43					
44	B No-44					
45	B No-45					
46	B No-46					
47	B No-47					
48	B No-48	30437	30711	32058	33568	34283
49	B No-49					
50	B No-50					
51	B No-51					

Certified by

Asst. Project Manager/Engineer
Modi Realty (Miryalaguda) LLP

S No.	Block /Flat No	After brick work	After Plastering	Stage I, Plumbing & electrical	Stage II	Stage III
52	B No-52					
53	B No-53					
54	B No-54					
55	B No-55					
56	B No-56					
57	B No-57	31028	32953	34401	34732	34951
58	B No-58					
59	B No-59					
60	B No-60					
61	B No-61	30981	31609	32145	33640	34284
62	B No-62	31508	32077	32775	33892	34449
63	B No-63	31536	32078	32946	34450	34505
64	B No-64	31537	32079	32947	33829	34474
65	B No-65	33977	34333			
66	B No-66	33909	34334			
67	B No-67					
68	B No-68					
69	B No-69					
70	B No-70					
71	B No-71	34945				
72	B No-72					
73	B No-73					
74	B No-74	32199	32443	33639	34740	
75	B No-75	33041	33773	34418	34726	
76	B No-76	31177	33074	33465	34825	
77	B No-77	31957	32264	33466	34363	34506
78	B No-78	34838				
79	B No-79	31750	32379	33570		
80	B No-80	31822	32288	33642	34400	34507
81	B No-81					
82	B No-82					
83	B No-83	34982				
84	B No-84					
85	B No-85					
86	B No-86	33194	33580	34690		
87	B No-87	34408	34623	34806		
88	B No-88	34191	34399	34906		
89	B No-89					
90	B No-90					
91	B No-91	33108	33566	34534		
92	B No-92	34320	34728			
93	Club House					

Certified by


Asst. Project Manager/Engineer
Modi Realty (Miryalaguda) LLP