

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. 1027

Date : _____


Project: AMR @ Naclan Mallapur

Account :- Parl - 3rd slab & Block - A
(Flat no - 103, 104, 106 and
107 + Condo)

Date of Inspection : 9-7-2020

checked shuttering members
and observations are as follows

1) chairs missing under cracked members
of slab



2) Cover blocks placed both sides and
bottom of beams

3) Seal all minor openings

4) Leave slabs for future entrance slabs
concrete

5) Provide column development bars

Engineer Sign

[Handwritten Signature]
9/7/20

Consultant Sign.

Date :

[Handwritten Signature]
Date : _____