

NR  
D/R

## SURVEY REPORT ON 26.04.16 OF NILGIRI HOMES

### VILLA NO: 05

- Ground floor bedroom handles are loosely fixed
- For Ground floor bedroom window Grill is not installed
- Proper cleaning measures to be taken
- 1<sup>st</sup> floor toilet paint/lupum has dropped down on tiles
- Final coat of painting is remained
- Electric switch boards are reviewed once again
- Cleaning of wardrobes shall be done
- Covering of laminates shall be removed

### VILLA NO: 21

- cleaning shall be done
- electric switches shall be reviewed once again

**Note:** As per directions of Shri Soham sir kitchen designs are going to be changed in both the villas

29/4/16  
30/4/16.

## SURVEY REPORT ON 26.04.16 of BNC ESTATES

### 'B' BLOCK FLAT - 101

- False ceiling paneling shall be cleaned
- Switch boards are reviewed once again
- Balcony glass granite framing around it was cleaned

*Handwritten signature*  
30/4/16

## SURVEY REPORT ON 28.04.16 of PMR -II

203

- Kitchen cabinet works are in progress

201


- Bedroom wardrobe handles are not fixed

*Handwritten signature*  
21/4/16


SURVEY REPORT ON 28.04.16 of VISTA HOMES

B-105

- Channels are missing




- Drawer is hitting to the shutter handel




*20/4/16*  
*30/4/16.*

➤ Skirting problem




---


➤ Washroom door is not closing properly




e- Door topper damaged



e- Skirting problem



Left in covered



## SURVEY REPORT ON 29.04.16 of SERENE FARMS

### COTTAGE no: 34

- Tiles are completed in all rooms except toilet
- False ceiling framing has completed

### VILLA no: 35

- False ceiling framing has completed
- Tiles in one bedroom has completed
- In master bedroom tiling works is in progress

*M. P. L.*  
30/4/16