

ME
7/12

Nilgiri Estates-II						
QC check						
Date: 24-11-2015						
Prepared By: Sunil						
S No	Villa No	Stage of work	QC request made default- Y/N	QC inspection default - Y / N	Remarks	
1	1	work not yet started	NA	NA		
2	2	work not yet started	NA	NA		
3	3	work not yet started	NA	NA		
4	4	work not yet started	NA	NA		
5	5	work not yet started	NA	NA		
6	6	Footing	Yes	Yes		
7	7	Footing	Yes	Yes		
8	8	work not yet started	NA	NA		
9	9	Col-1	Yes	Yes		
10	10	Plinth Beam	Yes	Yes		
11	11	Plinth Beam	Yes	Yes		
12	12	work not yet started	NA	NA		
13	13	work not yet started	NA	NA		
14	14	work not yet started	NA	NA		
15	15	work not yet started	NA	NA		
16	16	col-2	Yes	No		
17	17	col-3	Yes	No		
18	18	col-1	Yes	Yes		
19	19	work not yet started	NA	NA		
20	20	work not yet started	NA	NA		
21	21	Plinth Beam	Yes	Yes		
22	22	col-1	Yes	Yes		
23	23	Slab-1	Yes	Yes		
24	24	Slab-3	Yes	Yes		
25	25	work not yet started	NA	NA		
26	26	Footing	Yes	Yes		
27	27	col-2	Yes	Yes		
28	28	col-2	Yes	Yes		
29	29	Plinth Beam	Yes	Yes		
30	30	Plinth Beam	Yes	Yes		
31	31	col-1	Yes	Yes		
32	32	col-2	No	No		
33	33	col-3	No	No		
34	34	Plinth Beam	Yes	Yes		
35	35	work not yet started	NA	NA		
36	36	work not yet started	NA	NA		
37	37	work not yet started	NA	NA		
38	38	work not yet started	NA	NA		
39	39	work not yet started	NA	NA		
40	40	work not yet started	NA	NA		
41	41	work not yet started	NA	NA		
42	42	work not yet started	NA	NA		
43	43	work not yet started	NA	NA		
44	44	work not yet started	NA	NA		
45	45	work not yet started	NA	NA		
46	46	work not yet started	NA	NA		
47	47	work not yet started	NA	NA		

48	48	work not yet started	NA	NA	
49	49	work not yet started	NA	NA	
50	50	work not yet started	NA	NA	
51	51	work not yet started	NA	NA	
52	52	slab-2	Yes	Yes	Report to be submit.
53	53	work not yet started	NA	NA	
54	54	work not yet started	NA	NA	
55	55	col-2	Yes	Yes	
56	56	slab-2	Yes	Yes	
57	57	work not yet started	NA	NA	
58	58	col-1	Yes	Yes	
59	59	col-2	Yes	Yes	
60	60	Footing	Yes	Yes	
61	61	slab-2	Yes	Yes	
62	62	slab-3	Yes	Yes	
63	63	slab-4	Yes	Yes	
64	64	Footing	Yes	Yes	
65	65	slab-2	Yes	Yes	
66	66	work not yet started	NA	NA	
67	67	work not yet started	NA	NA	
68	68	Footing	Yes	Yes	Report to be submit.
69	69	work not yet started	NA	NA	
70	70	Footing	Yes	Yes	
71	71	Footing	Yes	Yes	
72	72	Footing	Yes	Yes	Report to be submit.
73	73	Brick work	Yes	No	Work not completed.
74	74	Footing	Yes	Yes	Report to be submit.
75	75	Plinth Beam	Yes	Yes	Report to be submit.
76	76	Footing	Yes	Yes	Report to be submit.
77	77	work not yet started	NA	NA	
78	78	work not yet started	NA	NA	
79	79	Plinth Beam	Yes	Yes	Report to be submit.