

aruna@modiproperties.com

From: "Soham Modi" <sohammodi@modiproperties.com>
Date: 14-08-2017 12:13 PM
To: aruna@modiproperties.com
Subject: LW: Plastering work was done before checking at headroom.

Print

From: akhilesh@modiproperties.com [mailto:akhilesh@modiproperties.com]
Sent: 11-08-2017 11:58
To: Soham Modi <sohammodi@modiproperties.com>
Cc: Nilgiri Estates <nilgiri.state@modiproperties.com>; Radhe Shyam <radheshyam@modiproperties.com>
Subject: Plastering work was done before checking at headroom.

MD sir,

As per our instructions plastering work at model villas has not be started before QC checking. Already I noticed contractor not to start work with out Qc check but they started plastering work at head room and parapet wall in villa no 101

This is for your kind information

With regards,

R Akhilesh