

Measurement of power at nilgiri state

Sl no	description	Reading on DG	Reading on power	remarks
1	Blue wire	238	200	Front of club house
2	red	240	210	do
3	yellow	240	240	do
4	blue	-	226	Near villa no-100
5	red	-	231	do
6	yellow	-	230	do
7	blue	-	239	Near main new meter no-1076
8	red	-	237	do
9	yellow	-	236	do
10	blue	-	236	Near main old meter no-1438
11	red	-	232	do
12	yellow	-	238	do
13		220	--	With load
14		240	--	Without load

SL

Checked along with rajreddy electrician and with RO person.

- 1. Single phase RO in running condition
- 2. Three phase RO in fuse problem
- 3. Provided new fuse but not working
- 4. RO people said tomorrow or day after tomorrow clear the issue

Best regards

Radheshyam