QC Audit Report

Date		28-03-2019		Prepared by	P.Sai Kumar.	
Project NILGIRI ESTA		STATES	Company	NILGIRI ESTATES		
For month beginning data 20 00 10				27.03.19	71123	
Sl No.						
1.	Are all plans filed as per Internal memo no. 917/5?					Remarks
2.	Are provision for curing adequate?					Yes
3.	Is temporary electrical points for construction provided on each floor/villa?					Yes Yes
	Moot vina:					
4. 	Is temporary electric power connection provided around the site with 10 sq mm cable and DBs?					Yes
5.	Are DBs for temporary electrical power connection locked?					No
6.	Is power connection in labour quarters secured and safe?					Yes
7.	Is curing being done for 21 days (check procedure and enquire with workers)?					Yes
8.	Is proportion box being used (check availability and enquire with workers)?					Yes
9.	No. of recron packets consumed during the month?					122
10.	Are safety belts and helmets regularly used?					
11.	Are CC cubes being sent for testing regularly?					NA
12.	Any default in proceeding with work without QC inspection at any stage? Give details					Yes No
13.	Recommendation for imposition of fines as per circular no. 607(a).					
14.	No. of consultants visits. Enclose scanned copy of consultants report.					-
Comments:						-
Suggest			· · · · · · · · · · · · · · · · · · ·			
		ishin - O				· · · · · · · · · · · · · · · · · · ·
read all	nis, r in Circular	ishing Comp 's related to	teted Villas are	not locking. Site-Eng	gineer's Akhil & /	Anil has to

Notes: 1. Report to be submitted once a month for each site. 2. Sites include PMRII, Vista, MNM, SOB III, GWE, KNM, Mehdi and other new sites. 3. Report must be send by email to M.D. and project manager in PDF format. 4. Confidential comments may be sent to M.D. by separate email. 5. Include photographs whenever necessary.

