

Details of pumps at Site							
Company:	G.V.R.C						
Project:	Imnopolis						
Prepared By:	G venkatesh						
Date:	16-10-2020						
S.no	Type of pump	Brand/model	Capacity/HP	No's	Operating system	status	Remarks/Location
1	Dewatering diesel pump	Kirloskar	3	1	Diesel	Working	internal tranferred to GVDC site.
2	Dewatering mono block pump	Kirloskar	5	1	Electrical	Working	at 4545 block
3	Bore well pump	KSB	1.5	1	Electrical	Working	at 5600S
4	Bore well pump	KSB	3	1	Electrical	Working	at N side beside naala
5	Dewatering mono block pump	Kirloskar	3	1	Electrical	Working	at 4545 block
6	Dewatering mono block pump	Kirloskar	3	1	Electrical	Not working	at repair shop thurkapally
7	Dewatering submersible pump	Kirloskar	1.5	1	Electrical	Not working	at repair shop thurkapally
8	Dewatering mono block pump auto on/off	KSB	1.75	1	Electrical	Not working	at repair shop rani gunj
9	Dewatering submersible pump	KSB	3	1	Electrical	Working	at 2727 lift pit
10	Dewatering submersible pump	KSB	3	1	Electrical	Working	at 2727 lift pit
11	sub mercible/Self priming pump	KSB	5	1	Electrical	Working	at 4545 block pumping station
		Total		11			
		Working		8			
		Not working		3			

APPROVED BY

G. Venkatesh
Project Manager