BRGV / MCMET / MGA Equipment details

Project	BRGV	Prepared by : Pushpa latha			
Site	MRGV		Date 30-11-2020		
SI.No	Equipment name	Location	Quantity	Remarks	
3	03 HP Dewatering pump	Compound wall beside	1	Working Condition	BRGV
	02 HP Dewatering pump	compound wall beside	1	working Condition	BRGV
	3 1.75HP Dewatering pump	In the middle of Site(In water)	1	working Condition	BRGV
	02 HP Openwell Pump	Lift Pit	1	working Condition	MCMET
	01 Hp Openwell Pump	Store	1	working Condition	MCMET
6	01 HP Dewatering pump	Lift Pit	1	working Condition	MGA
Electricity	Meter Nos	Location	Quantity		
1	0110-00847	BRGV	1	working Condition	
2	0110-00667	MCMET	1	working Condition	
3	0110-00737	MGA	1	working Condition	
Submeter	<u> </u>		Quantity		
1	12373	Site offfice	1		
2	11098	Labour quarters	1		
3	258189	MGA	1		
4	16105	MCMET	1		
CC Cameras			Quantity	D-Link Airtel Sim No	
1	CC Camera	BRGV Tower	1	9154109051	
2	CC Camera	BRGV Tower	1	9154109051	
3	CC Camera	MGA	1	7671078192	
Modem			***************************************		
1	Jio-Modem	7569652731	Site office		**********************
Genrator					
	Genrator	Kirloskar 15kva	1	No	

APPROVED BY

3 0 NOV 2020

T. MADHU PROJECT MANAGER B.R.G.V