

BRGV / MCMET / MGA
Equipment details

Project	BRGV		Prepared by : Pushpa latha		
Site	MRGV		Date 31-12-2020		
Sl.No	Equipment name	Location	Quantity	Remarks	
1	03 HP Dewatering pump	Compound wall beside	1	Working Condition	BRGV
2	02 HP Dewatering pump	compound wall beside	1	working Condition	BRGV
3	1.75HP Dewatering pump	In the middle of Site(In water)	1	working Condition	BRGV
4	02 HP Openwell Pump	Lift Pit	1	working Condition	MCMET
5	01 Hp Openwell Pump	Store	1	working Condition	MCMET
6	01 HP Dewatering pump	Lift Pit	1	working Condition	MGA
Electricity	Meter Nos	Location	Quantity		
	1 0110-00847	BRGV	1	working Condition	
	2 0110-00667	MCMET	1	working Condition	
	3 0110-00737	MGA	1	working Condition	
Submeter			Quantity		
	1 12373	Site office	1		
	2 11098	Labour quarters	1		
	3 258189	MGA	1		
	4 16105	MCMET	1		
CC Cameras			Quantity	D-Link Airtel Sim No	
	1 CC Camera	BRGV Tower	1	9154109051	
	2 CC Camera	BRGV Tower	1	9154109051	
	3 CC Camera	MGA	1	7671078192	
Modem					
	1 Jio-Modem	7569652731	Site office		
Genrator					
	1 Genrator	Kirloskar 15kva	1	No	

31 DEC 2020
T. MADHU
PROJECT MANAGER B.R.G.V.

For
nd. f. Salmes