Remarks from site on the 'Requisition by Site Report' of purchase division

Date:

27.03.2021

Modi realty Mallapur LLP

Company:

Site:		Gulmohar residency			Prepared by:		M.Likhitha		
Report From /		21.03.202	21 to 27.03.	.2021	Approved by:		Ram Prasad		
•		(Sunday t	to saturday)						
Report Date 27.03.202			21						
		s numbers	missing in	the repo	ort :				
List of requ	isition	is where Po	O/WO not p	repared	3 working day	s afte	r requisition:		
Req No.		eq Date	S.no		Description Reason for not preparing PO/WO*				
68836	68836 15.03.2021		1	Pre laminated sheets 12mm thickness					
List of requ	isition	ns where Po	O/WO is pro	epared a	nd items have n	ot be	en received at site beyond the lead		
Req No. Req Dat		eq Date	Serial no of item in Req.	Item Description		Details of discussion with supplier\$			
68745	10.0	2.2021	1	MS St	and		Po.No. 74749- No stock at SSLLP		
68750		2.2021	1	Bathroom tiles		Po.No. 74787- No stock at SSLLP			
68751		2.2021	1	Bathroom tiles		Po.No. 74788- No stock at SSLLP			
68757	12.0	2.2021	1	Panel o			No. 74798- No stock at SSLLP		
68758	12.0	2.2021	1	Panel o	doors shutters	stoc	No. 74797- partly recieved No k at SSLLP		
68782	22.0	2.2021	1	Pannel	door shutters	Po.N	No. 75160- No stock at SSLLP		
68784	23.0	2.2021	1			NO - 75149 No stock at SSLLP			
68787	23.0	2.2021	1	Blanco	white	PO	NO - 75150 No stock at SSLLP		
68789	23.0	2.2021	1	Templ	ates		NO - 75211 No stock at SSLLP		
68795	24.0	2.2021	1	PVC p	ipe	1	NO - 75159 partly recieved no k at ssllp		
68800	24.0	2.2021	1	Panel o	doors	Po.N	No. 75174- No stock at SSLLP		
68804	25.0	2.2021	4	PVC p	ipe s/socket		No. 75261 partly recieved- No k at SSLLP		
68809	02.03	3.2021	1	Ventila	ators	arrai	No. 75449,75499,75500- supplier nging for material		
68825	09.03	3.2021	1	Regal	beige		No. 75541- No stock at SSLLP		
68826	09.03	3.2021	1	Regal	beige		No. 75511- No stock at SSLLP		
68827	09.03	3.2021	1	Regal			No. 75686- No stock at SSLLP		
68841	16.03	3.2021	1		om tiles	_	No. 75684- No stock at SSLLP		
68842	16.03	3.2021	1	Padloc			No. 75625- No stock at SSLLP		
68845	16.03	3.2021	1	PVC si	ngle socket	PO 1	NO - 75646. No stock at SSLLP		
68846	16.03	3.2021	1	PVC F		mate			
68847	17.03	3.2021	1	Roff ac	dhesive		No. 75687- No stock at SSLLP		
68853	19.03	3.2021	1	granite		Po.N	No. 75805- Next week delivery		

68854	20.03.2021	1	CPVC		Po.No.	75802-	Next week delivery		
68856 20.03.2021		1	Wires		Po.No.	75804-	Next week delivery		
68857 24.03.2021		1	40Am	ps Isolator	Po.No.	75809-	Next week delivery		
68858	1	_	adhesive	Po.No. 75799- No stock at SSLLP					
68863	1	Lappu	ım	Po.No. 75888- Next week delivery					
68864	58864 24.03.2021 1			Lappum		Po.No. 75887- Next week delivery			
No. of gate	passes issued thi	is week:	1	From No.	2721	To)		
Delivery van site visit on: 23.03.2021(Tuesday), 25.03.2021(thursday), 27.03.202									
(saturday)									
Inward repo	ort (MRN/other)	& stock rep	ort ema	ort emailed in pdf format to			Yes		
DC register Sl. No. during the week From			n No.	2082		To No.	No. 3033		
Items not o	rdered but receiv	ed: nil			•				
Items sent	to HO /vendor th	at are pend	ing for r	epair: 2 motors (submer	ssible pu	imps)		
Other corre	ections & remark	S:							
Details	Details Project Manage					Admin Audit			
		da	2	Officer/Manag	er				
Sign	162	V	•	Linkish	2				
Date	1	27/3/2	-1	0	1/3/				

Notes: 1. * Send a copy of the missing requisitions to Purchase immediately. 2. Send this report purchase@modiproperties.com, ashaiya@modiproperties.com rajkumarn@modiproperties.com on every Saturday. 3. Admin offices shall not leave the site without completing this report. 4. Ensure that inward numbers are written on the Requisitions, 5. Mention PO & MRN no. on DCs / clearly showing the items not received on a daily basis. bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks - For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. \$ Suggested remarks - Ready with supplier, Supplier not contacted, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for fabrication not received, WO - material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up – DO NOT CALL PURCHASE!