BRGV / MCMET / MGA Equipment details

Project	BRGV		Prepared by : Pushpa latha	
Site	MRGV		Date15-04-2021	
2	Equipment name	Location	Quantity	Remarks
	1 03 HP Dewatering pump	Compound wall beside	1	Working Condition
	2 02 HP Dewatering pump	compound wall beside	1	working Condition
	3 1.75HP Dewatering pump	In the middle of Site(In water)	1	working Condition

APPROVED BY

APR 2021

T. MADHU
PROJECT MANAGER B.R.G.V