

Company :		Modl Properties pvt.ltd			Approved By		S.V.Subba Reddy	
Project :		May flower Platinum			Date :		10.07.2021	
Contractor Details :		MPL			Quarterly report		April to June	
Prepared By :		B.Nandini						
SI No :	Item Description	Make	Type	Capacity	Quantity	Units	Installed	Status
1	Submersible Pump	KSB	Electrical	3 HP	4	No's	At corners of site NW, SE, SW & NE	Working
2	Submersible Pump	KSB	Electrical	2.5 HP	2	No's	Fixed at B block lifts	Working
3	Submersible Pump	KSB	Electrical	3 HP	1	No's	Fixed at C block lift.	Working
4	Cutter Pump	KSB	Electrical	2.5 HP	2	No's	Fixed at south side and NE septic tanks	Working
5	Cutter Pump	KSB	Electrical	2.5 HP	1	No's	At Store	Working
6	Submersible Pump	KSB	Electrical	1 HP	1	No's	NW corner harvesting pit	Working
7	Submersible Pump	KSB	Electrical	5 HP	1	No's	For Site use purpose	Working
8	Auto level instrument complete set	Bosch	Electrical	-	1	No's	At office	Working
9	Breath analyser	-	Electrical	-	1	No's	For Site use purpose	Working
10	Sand screening machine	-	Electrical	-	1	No's	For Site use purpose	Working
11	Compaction machine	-	Electrical	-	1	No's	For Site use purpose	Working
12	Laser line instrument	-	Electrical	-	1	No's	For Site use purpose	Working
13	RO Water plant	Aqua System	Electrical	500lit/hr	1	No's	To be installed	Working
14	Generator	Mahindra	Electrical	25KVA	1	No's	For Site use purpose	Working
15	Sub meter	HPL electrical	Electrical	-	1	No's	For site bore purpose at NE corner	Working
16	Sub meter	HPL electrical	Electrical	-	1	No's	For site bore purpose at SE corner	Working
17	Sub meter	HPL electrical	Electrical	-	1	No's	For site bore purpose at NW corner	Working
18	Sub meter	HPL electrical	Electrical	-	1	No's	For site bore purpose at SW corner	Working
19	Sub meter	HPL electrical	Electrical	-	3	No's	Labour quarters	Working
20	Sub meter	HPL electrical	Electrical	-	1	No's	RO Plant	Working

10/7/2021

APPROVED BY
10 JUL 2021
S.V. Subba Reddy
Project Manager