9								
Not Working	send to repair	No's	1	2HP/3 Ph	Electrical	kırlosker	oben wen anomersione bumb	
Not Working	send to repair	No's	1	2HP/3Ph	Electrical	KIIOSKET	Open usell Submary Line pump	
working	Store	No's	_	5HP/3Ph	Blectrical	7.30	Open well Stihmersihle nump	
borewell water comes for 5mins	Club house	No's	1	3HP/3ph	Diecuical	V CD	Cutter type seewage primp	13
curing purpose	Club house lift pit	No's	-	THY/THC.1	Electrical	kirlosker	submersible pump Borewell	12
Not Working	G-Block north side	No's	1./2	5HP/3Ph	Electrical	KSB	Open well Submersible pump	11
Curing purpose	G-Block lift pit	No's	-	IHP/2Ph	Elecuical	kirlocker	submersible pump borewell	10
Curing purpose	F-Block lift pit	No's	1	1.5 hp/1ph	Electrical	KSB	Open well Submersible pump	9
Curing purpose	D-Block lift pit	No's	-	1.5 hp/1ph	Discursal	KSB	Open well Submersible pump	∞
Rain water removing 40' depth	west side comound wall	No's	1	1.5 HP/1 Ph	Electrical	KSB	Open well Submersible pump	7
All blocks water supply 1400' rft	C-Block gate entrance	No's	1	7.5 HP/3 Ph	Precitical	kirlosker	Open well Submersible pump	6
Curing purpose	C-Block	No's	1	1.5HP/1 Ph	Electrical	kirlosker	submersible pump Borewell	
Curing purpsoe	B-Block	No's		3 HP/3 ph	Flectical	KSB	Open well Submersible pump	4
no borewell water	Borewell at A-Block	No's	-	3 IP/3 Ph	Floorical	KSB	Open well Submersible pump	
Curing purpose	A-Block lift pits	No's	1	2HP/1 Ph	Electrical	KSB	Open well Submersible pump	2
	8 4					VCD	Open well Submersible pump	
Status	Installed	Units	Quantity	Capacity	Туре	Make		
							Item Description	SI No :
							A.Sravani	r repared by:
			77	120	13.07.2021	Date:	_	Prenand B.
					Ram prasad	Approved by:		Project:
						A	Company: Modi Realty Mallapur LLP	Company:

