BRGV / Equipment details

Company	BRGV		Prepared by : Pushpa latha		
Project	MRGV		Date 16-07-2021		
2	Equipment name	Location	Quantity	Remarks	
	03 HP Dewatering pump	Compound wall beside	1	Working Condition	BRGV
	02 HP Dewatering pump	compound wall beside	1	working Condition	BRGV
	1.75HP Dewatering pump	In the middle of Site(In water)	1	working Condition	BRGV
7 10					

1 6 JUL 2021

T. MADHU PROJECT MANAGER B.R.G.V