C	,	1	D 1. 1.7	Section Section Company Company					- Miles in the second second second
Company:			Realty Miryalagi	The Party of the P			-13-09-2021		
Site: A'		AVR	Gulmohar Home	\$	Prepared by:	red by:		Zakir	
Report From ≠ To 04-09		04-09	-2021 to 12-09-2	021	Approved by:				
Report Date 13-09-			-2021					er sammen and desired an enterior	
List of requisitions numbers missing in the report:									
List of requisitions where PO/WO not prepared 3 working days after requisition:									
Req No.	Req Date		Serial no of item in Req.	Item Description		Reason for not preparing PO/WO			
165442	18-08-2021		1	SS Screws		PO to be issue			
165459	03-09-2021		1 to 09	Bathrrom tiles		PO to	be is	sue	
165462	_ 1	9-2021	1 to 07	AL windows		PO to be issue			
165463	03-09-2021		1 to 07	Windows grill		PO to be issue			
165464	_	9-2021	1	Ten brawn		PO to be issue			
165465		6-2021	1	Lappum		PO to be issue			
165470		9-2021	1 to 5	Tower bult		PO to be issue			
List of requisitions where PO/WO is prepared and items have not been received at site beyond the lead time:									
Req. No.	Rea	. Date	Serial no of	Item	Details of discussion with supplier				
-	req. Date		item in Req.			Details of discussion with supplier			
		5-2021	-3	S.C.Grigio		90% material received at site			
165411	-	7-2021	1	Villa no.70 tiles		70% received;			
165413		7-2021	20 & 21	Panel doors clubhouse		Ready to supplies			
165412	03-07	7-2021	1	Villa no.60 tiles		Ready to supplies			
165423	26-07	7-2021	1,23 &5	Z angle templates		Ready to supplies			
165427	26-07	7-2021	1 to3	Villa no.18 tiles		Ready to supplies			
165431	26-07	-2021	1&3	Window grills		Ready to supplies			
165439	21-08	-2021	1	Vitrified tiles		_		pplies	
165440	17-08	3-2021	10 & 38	CPVC materials		Ready to supplies			
165445	20-08	-2021	1 to 04	Plants		Ready to supplies			
165447	21-08	-2021	1	Tendur Stone		Ready to supplies			
165448	23-08	-2021	1	CC TV camera		Ready to supplies			
165449	23-08	-2021	2	LED bulb		Ready to supplies			
165450	23-08		1 to 11	CP materials		Ready to supplies			
165451	23-08		2	Wash basin		Ready to supplies			
165452	25-08		03	SS cylind.lock		Ready to supplies =			
165455	25-08		1	LED light					
165458	04-09		1	Vitrified files		Ready to supplies			
165459	04-09		1 to 12	Bathroom tiles		Ready to supplies			
165460	04-09	-	1 to 12	Utility Tiles		Ready to supplies			
165461				Panel door		Ready to supplies			
165466	04-09		lto 6			Ready to supplies			
		03-09-2021 1,3,5,6		4x2 tiles			Ready to supplies		
165467		0-2021 1,2,5,6		4x2 tiles		Ready to supplies			
165458	03-09-		4,6	4x2 tiles		Ready to supplies			
65469 08-09-2021 1 to 12			Bathroom tiles		Ready to supplies				
No. of gate pas				Have	From No.	1438		To No.	1442
Delivery van last site visit on: 04-09-2021									
nward report (MRN/other) & stock report emailed in pdf format to Yes									
ourchase? OC register Sl.No. during the week From No. 148849 To No. 148858									
tems not ordered but received:									
Other corrections & remarks: We have send 2.5HP Submersible pump for repairing purpose to SVR pump									
service center	service center also we have sent 2.2 HP submissible pump,3.cutting machine and 4. Drilling machine for								
repairing purpose									

Louis	i roject jiranager	Trainin Officer manager Hamin Haan
Sign	dia	
Date		

Notes: 1. * Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to purchase modiproperties.com, ashaiya@modiproperties.com and rajkumarn@modiproperties.com on every Saturday. 3. Admin offices shall not leave the site without completing this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis. 5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks – For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. Suggested remarks - Ready with supplier, Supplier not contacted, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for fabrication not received, WO - material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site – purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up – DO NOT CALL PURCHASE!