## BRGV Equipment details

Company:	MRGV		Prepared by: Pushpalatha	
Project:	BRGV		Date: 23.10.2021	
SI.No	Equipment Name	Location	Quantity	Remarks
1	3 HP Dewatering Pump	Compound wall beside	1	Woring condition
2	2HP Dewatering Pump	Compound wall beside	1	Installing on Monday
3	1.7HP Dewatering Pump	in the middile of site (in water)	1	Installing on Monday

