Compar	ny:	MCMET						
Project	& Phase:	MLMMH		11				
Prepare		S.Sunil Kun	nar					
Report Date:		07.10.2021						
Sign:								
Check li	ist for QC at each stage.							
Notes:								
1. R	eport should be send once	a quarter on or b	pefore 15th o	the succeed	ling month.			
	here QC was done write t							
3. M	fark 'X' if QC check was m	issed and can be	taken up nov	w. Project M	anager to se	end request in	nmediately.	
4. M	lark 'XX' if QC check was	missed and cann	ot be underta	ken now.		1		
5. M	lark 'NA' if QC check was	not applicable (work done be	efore QC wa	s introduced	i).		
	eave blank if work has not							
Remarks	s:							



C HOIKS	- Apariment	DIOCES																
	Block .	Before	Plinth		at i													
S No	Villa No.		Pilinth	Col 1	Slab 1	Col 2	Slab 2	Col 3	Slab 3	Col 4	Slab 4	Col 5	Slab 5	Col 6	Slab 6	OTH & lift	drive-way	drive-
	1	35595 3564	35780	35931	35961/360	36124	36257	2620	6 36508/363	24///2	24441.244					гретт	col	sla
		7:35588:35			43 36257		302,47	3639	10000	36662	36661/368		37138			37436		
		643/35709			40.002.07				97		6.3							
- 1																		
1																		

S No.	Block /Flat	After brick work	After Plastering	Stage I, Plumbing & electrical	G. II	_	
1	1st floor	37265	1 lastering	electrical	Stage II	Stage III	Rem
2	2nd floor	37604					
3	3rd floor	37873					
4	4th floor	38398					
5							
6							
7							
8							-
9							
10							
11							
12							
13							
14							-
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26		,4:					
27							
28							
29							
30							
31							
32							
33							
34							
35							
36							
37							
38					-		·
39							
40							
41							
42							
43							
44							
45							
46							
47							
48							
49							
50							
51							
52							
53							
54							