


List of Pumps and Equipment details of BRGV

Company	MRGV		Prepared by : Pushpa latha	
Project	BRGV		Date 18-01-2022	
S.No	Equipment Name	Location	Quantity	Remarks
1	3 HP Dewatering Pump	Compound wall Beside	1	working Condition
2	2 HP Dewatering pump	Store	1	working Condition
3	2 HP Dewatering pump	In The middle of Site	1	working Condition
4	3 HP Submersible Pump	Near Compound wall	1	working Condition
5				


 18-01-22